

Date: February 21, 2011

Subject: 15K Service Hubs

At the beginning of 2004, Dexter Axle changed their 15K hub offering from 6 or 10 bolts on an 8.75" bolt circle to the current 8 bolt on 275mm bolt circle. The 6 and 10 bolt inventory is almost depleted and the supplying foundry for those castings is out of business. There is a limited quantity of parts still available, then we will no longer offer these parts as service replacements once those are gone.

Available While Supplies Last

Part Number	Description	Quantity
008-217-09	6 on 8.75 RH Hub	18
008-217-29	6 on 8.75 LH Hub	25
008-217-05	10 on 8.75 RH Hub	18
008-217-25	10 on 8.75 LH Hub	18

After this inventory has been depleted, you will need to replace the hub with an 8 on 275mm. This will require the replacement of the wheel with one that has the 8 on 275mm bolt pattern. The drum 009-028-01 will still be available.

We regret any inconvenience this may cause. Please contact your Dexter sales engineer if you have additional questions or need further assistance.



Rick Kapsa
Product Manager