

Date: May 16, 2022

Subject: DX8.5L with 2-5/16" Coupler Replacing Former UFP A-84 Surge Actuator

Dexter is discontinuing the former UFP-A84 surge actuator and replacing the A84 with the Dexter DX8.5L surge actuator with 2-5/16" coupler. The DX8.5L with 2-5/16 coupler is the companion surge actuator to the DX8.5L with 2" coupler (formerly UFP XR84).

Going forward, several configurations of the A84 will not be offered in the DX8.5L 2-5/16" coupler configuration; refer to the tables in this bulletin for the configurations that are being retained or discontinued.

Below are the DX8.5L with 2-5/16" couplers being offered:




Inner Members

PART NUMBERS	DESCRIPTION	REPLACES
099-384-00	Inner Member, Drum	099-084-00
099-384-10	Inner Member, Disc w/Solenoid, Single Axle	099-084-10
099-384-20	Inner Member, Disc w/Solenoid, Tandem Axle	099-084-20
099-384-30	Inner Member, Disc w/Solenoid, Triple Axle	099-084-30



Complete Surge Actuators

PART NUMBERS	DESCRIPTION	REPLACES
099-384-04	Drum, Zinc, Bolt-on, Top Mount, 14.5" Long, Single Axle (S Mount)	099-084-04
099-384-23	Disc, Primed, Bolt-on, In-line Mount, 19" Long, 3"x5" Straight Tongue for Tandem Axle (SXL Mount)	099-084-23
099-384-24	Disc, Zinc Bolt-on, Top Mount, 14.5" Long, Tandem Axle (SXL Mount)	099-084-24
099-384-25	Disc, Zinc, Bolt-On, In-line Mount, 19" Long for 3"x4" Straight Tongue (XL Mount)	099-084-25
099-384-2H	Disc, Primed, 5" Swing Tongue (OEM Only Item) (Contact your Dexter Account Manager for Mounting Diagram)	New



DISCONTINUED SURGE ACTUATORS PART NUMBERS		
099-084-01	099-084-18	099-084-32
099-084-02	099-084-21	099-084-33
099-084-03	099-084-22	099-084-34
099-084-05	099-084-26	099-084-35
099-084-06	099-084-28	099-084-36
099-084-08	099-084-2C	099-084-38
099-084-15	099-084-31	099-084-3C

DISCONTINUED KIT PART NUMBERS
K99-084-00
K99-084-20

Please contact your Dexter account manager for additional information and further assistance.

Jay Klinkerman
Product Manager