

Date: June 16, 2022

Subject: Discontinuing 008-448-10 Idler Hub & Hub Kit

Due to customers no longer utilizing the 008-448-10 (Former UFP 33889) hub, it is being discontinued. There is no replacement for this hub, and users will need to replace their axle if the hub needs to be replaced.



Discontinued Hub & Hub Kit

PART NUMBERS	DESCRIPTION
008-448-10 Formerly UFP 33889	Idler Hub, 2.1K, 5 on 4.50" Bolt Circle
K08-448-10	Hub Kit Containing 008-448-10

Please contact your Dexter account manager for additional information and further assistance.



Jay Klinkerman
Product Manager